Application 10/707,174

## Top View of Submarine




Figure 1

### Top View of Submarine





Figure 2


Application 10/707,174

## Top View of Submarine



Application 10/707,174

## Top View of Submarine



# Figure 4

## Water Tight Chamber





Figure 5


Application 10/707,174

#### Picture 1



Application 10/707,174

Picture 2




Application 10/707,174


Picture 3



Application 10/707,174




Application 10/707,174



Application 10/707,174

#### Picture 6



# This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

#### **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:	
	☐ BLACK BORDERS
	☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
	☐ FADED TEXT OR DRAWING
	☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
	☐ SKEWED/SLANTED IMAGES
l	COLOR OR BLACK AND WHITE PHOTOGRAPHS
	☐ GRAY SCALE DOCUMENTS
	☐ LINES OR MARKS ON ORIGINAL DOCUMENT
	☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.